


点検結果一覧

橋梁番号	橋梁名	供用開始年月	供用年数	路線名	径間数	橋長	部材単位の診断結果					健全性の診断	コメント	
							上部構造			下部構造	支承部			その他
							主桁	横桁	床版					
12	鳴子坂橋	1990	30	林道萌出線	3	58.7	I	/	I	I	/	/	I	特になし
13	新鳴子坂橋	1999	21	林道萌出線	3	55.8	I	/	I	I	/	/	I	特になし
14	寺ノ沢橋	2002	18	林道寺ノ沢線	2	96.7	I	/	I	I	II	/	II	支承:変色・劣化(ゴム・プラスチック)

2.4 点検結果写真

No.12	鳴子坂橋	2019/10/24	No.13	新鳴子坂橋	2019/10/24	No.14	寺ノ沢橋	2019/10/24	
		NARU_1181.jpg ラーメン主構(脚):Rp0102 健全度 4.0			SNAR_1236.jpg ラーメン主構(脚):Rp0102 健全度 4.0			TRNS_3495.jpg 支承:Bh0101e 健全度 3.0	TRNS_0099.jpg 防護柵:Gf0101 健全度 4.0
		NARU_0074.jpg 床版(Co):Ds0102e 健全度 4.0			SNAR_1288.jpg 防護柵:Gf0201 健全度 4.0			TRNS_1294.jpg 排水管:Dp0101 健全度 4.0	TRNS_1301.jpg 橋台胸壁:Ap0101e 健全度 4.0
		NARU_1205.jpg ラーメン主構(脚):Rp0102 健全度 4.0			SNAR_0166.jpg 排水ます:Dr0201 健全度 4.5				